



CAUTION

The Lantronix MSS100-01-SSA with Version 3.6/3 firmware was specially setup to run the Sensorsoft SNMP Agent software.

Do not upgrade the Lantronix firmware or change any Lantronix settings on this unit, with the following exceptions:

IP ADDRESS
SUBNET MASK
NAMESERVER
DOMAIN
GATEWAY
PRIVPASS

Changing any other settings or upgrading the firmware will cause the Sensorsoft SNMP Agent software to stop running and will need to be sent back to the factory.

If you are having extreme difficulty setting your IP address and need to reset the unit to factory default, please refer to the Sensorsoft SNMP Agent User Manual for instructions on how to restart the Sensorsoft SNMP Agent software.